David Ward

From:

Gdylg#Z dug# gz dugC crxgrxqz lindiwvfrp A

Sent:

Wkxugd | #/hswhp ehu#57#5348#⇒3#DP

To: *5dwill5vdulv*#R wwr#T xwhqvrq*#HohdqrulP #Dgdp v*#DqqhlDdurq*EuxfhlYrkqvrq#

+euxfh5<;Cjpdbfrp,#Gdylg#Qhorq#gdqhorq533<Cjpdbfrp,

Subject: Ryhudsslqj#dufhow#w#Ihdwkhuehg#dqh#Eulgjh

I'll let you know what the Parcel Mapping Expert at Loudoun County comes up with.

From: Ward, David [mailto:David.Ward@loudoun.gov]

Sent: Thursday, September 24, 2015 8:45 AM **To:** Rubis, Glen <Glen.Rubis@loudoun.gov> **Cc:** info@loudounwatershedwatch.org

Subject: FW: How do I interpret overlapping parcels?

Doug is on it!

From: Ward, David

Sent: Thursday, September 24, 2015 8:35 AM

To: Packard, Doug

Subject: RE: How do I interpret overlapping parcels?

Thank you Doug!

From: Packard, Doug

Sent: Thursday, September 24, 2015 8:33 AM

To: Ward, David

Subject: RE: How do I interpret overlapping parcels?

Thanks David,

Unfortunately there is an error here. Even when a plat shows gores or gaps we shouldn't have one. The latest plat is not what is in the parcel layer for one of the items. It should display correctly tomorrow. I need to investigate to see what happened.

Thanks, Doug

From: Ward, David

Sent: Wednesday, September 23, 2015 4:19 PM

To: Packard, Doug

Subject: How do I interpret overlapping parcels?

Doug:

I noticed that there is an overlap between adjacent parcels. How do I interpret this?

299493233000 Waterford Downs with Plat 2000-0579 260254610000 Has no plat

261367996000 Waterford Downs Plat 2014-0281

This is the intersection where Featherbed Lane Bridge is located.



David Ward

<u>Water Resources Engineer</u>

Department of Building & Development

Loudoun County Government 1 Harrison St, MC #60 Leesburg, VA 20175 703-737-8670